


Remote Control Settings	Button	Remarks
-------------------------	--------	---------



Button	Remarks
ON/OFF	Permanent on/off
Reset	Return to sensor mode with preset target lux level
200Lux 300Lux 400Lux 500Lux 600Lux 700Lux 800Lux 900Lux	Setting target lux level 200–900Lux Note: 700/800/900 target lux level is NA for MS11
DMI+ DMI-	Adjust target lux level, each press +/- 10%